Approved For Release 2000/04/13 : CIA-RDP68B00320R000100070003-2

FORM 224 USE PREVIOUS EDITIONS

DATE

TO :

FROM :

ACTION:

INFO :

ROUTING

1		9	
2		10	
3		11	
4		12	
5		13	
6		14	
7		15	
8		16	

OVS 1-10 Sec

IN 55636

TO INFO CITE

25X1A

T O P S E C R E T 150600Z CITE [redacted] 7324

IMMEDIATE [redacted] INFO [redacted] 25X1A 25X1A

[redacted]

C136C 25X1A

REF: [redacted] 0052 25X1A

1. AIRCRAFT BEING CHECKED NOW TO DETERMINE ACTUAL HF OR BW PROBLEM. ANTICIPATE NOT MORE THAN 6 HOURS TO REPAIR OR REPLACE ENTIRE SYSTEM.

2. PILOT AND AIRCRAFT WISE WE SHOULD BE ABLE TO LAUNCH SAME OR MODIFIED MISSION ON 16 MAY, IF DESIRED [redacted] AGREES. 25X1C

3. STANDING BY FOR INSTRUCTIONS.

T O P S E C R E T TOR 0614Z 15 MAY 66

EDD
PH
RP
KB
DB
AF
NM
DJ

[redacted]

GROUP 1
EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

Approved For Release 2000/04/13 : CIA-RDP68B00320R000100070003-2
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.